

SERVICE PARTS LIST FOR MITSUBISHI ELECTRIC PACKAGED AIR-CONDITIONERS

Series : PEFY-W•VMS-A.TH

REVISED

July 2019

BWE01832B

INDEX

PEFY-W10VMS-A.TH

PEFY-W15VMS-A.TH

PEFY-W20VMS-A.TH

PEFY-W25VMS-A.TH

PEFY-W32VMS-A.TH

PEFY-W40VMS-A.TH

PEFY-W50VMS-A.TH

Part information update day : **2019/07/29**



Please change the old catalog (issued Mar. 2019, No.BWE01832A) to this new catalog.

Content of revision : Some of parts are changed.




PEFY-W10,W15VMS-A.TH
 PEFY-W20,W25,W32VMS-A.TH
 PEFY-W40,W50VMS-A.TH


EXTERNAL PARTS




A
 Detail of 2-way valve




Detail of Nipple




*1 Apply Grease (part No.113) to hatching part.






PEFY-W10,W15VMS-A.TH
PEFY-W20,W25VMS-A.TH
PEFY-W32,W40VMS-A.TH

CONTROL BOX PARTS (1)





mitsubishi
electric
corporation

BWE01832B (20190731)